



## 1. Embedded Systems Overview


1.2 Introduction and Performance Measures


































































## The Ariane 5 Failure (4 June 1996) On 4 June 1996 the maiden flight of the Ariane 5 launcher ended in a failure, about 40 seconds after initiation of the flight sequence. At an altitude of about 3700 m, the launcher veered off its flight path, broke up and exploded. The failure was caused by "complete loss of guidance and attitude information" 30 seconds after liftoff. To quote the synopsis of the official report: ٥ "This loss of information was due to specification and design errors in the software of the inertial reference system. The extensive reviews and tests carried out during the Ariane 5 development programme did not include adequate analysis and testing of the inertial reference system or of the complete flight control system, which could have detected the potential failure." Because of this conclusion, the accident has generated considerable public and private discussion amongst experts and lay persons. Code was reused from the Ariane 4 guidance system. The Ariane 4 has different flight characteristics in the first 30 seconds of flight and exception conditions were generated on both IGS channels of the Ariane 5. Failures often came not from the first, careful, conservative implementation of a 0 design, but from its extension. led System



25

